




A-SD850

1/2" SQ.DR.SUPER DUTY AIR IMPACT WRENCH



INDEX NO.	Parts No.	Description	Q'ty	INDEX NO.	Parts No.	Description	Q'ty
★01	SD85001	Motor Housing Assembly (incl.43)	1	24	SD85024	Screw	4
02	SD85002	Backhead	1	25	SD85025	Reverse Valve	1
03	SD85003	Ball Bearing	1	26	SD85026	Hammer Frame	1
04	SD85004	Rear End Plate	1	27	SD85027	Hammer	1
05	SD85005	Front End Plate	1	28	SD85028	Hammer Pin	2
06	SD85006	Ball Bearing	1	29	SD85029	Standard Anvil	1
07	SD85007	Rotor	1	30	SD85030	O-Ring	1
08	SD85008	Rotor Blade	6	31	SD85031	Socket Retainer	1
09	SD85009	Cylinder	1	32	SD85032	Bushing	1
10	SD85010	Air Inlet	1	33	SD85033	Spring Pin	1
11	SD85011	Spacer	1	34	SD85034	Spring Pin	1
12	SD85012	O-Ring	1	35	SD85035	Gasket	1
13	SD85013	Exhaust Deflector	1	★ 36	SD85036	Trigger Assembly (incl.36-1.36-2.36-3)	1
14	SD85014	O-Ring	2	● 36-1	SD85036-1	Trigger	1
15	SD85015	Throttle Valve Seat	1	● 32-2	SD85032-2	Trigger Pin	1
★ 16	SD85016	Throttle Valve Assembly (incl.16-1.16-2)	1	● 36-3	SD85036-3	O-Ring	1
● 16-1	SD85016-1	Throttle Valve Pin	1	37	SD85037	Spring Pin	1
● 16-2	SD85016-2	Throttle Valve	1	38	SD85038	O-Ring	1
17	SD85017	O-Ring	1	39	SD85039	O-Ring	1
18	SD85018	Spring	1	40	SD85040	Hammer Case	1
19	SD85019	Spring	1	41	SD85041	Spring Pin	1
20	SD85020	Reverse Valve Knob	1	42	SD85042	Muffler Element	1
21	SD85021	Pin	1	● 43	SD85043	Bushing	1
22	SD85022	Gasket	1	TK	Tune-Up Kit { incl.8 (6).12.14 (2).17.18.19.22.30.31.35.38.		
23	SD85023	Screw	1		39.42 }		
★Must be Purchased in Assembly Set			●	Recommended not to be purchased alone due to assembly difficulty			